

BUILDING SAFETY CERTIFICATE

No.

Dated: 05/12/2024

It is certified that the existing building ST. FRANCIS SCHOOL (name of the building or premises) at TANAKPUR (address)

is having block(s)/Floor(s) as per details below:

Details of Block(s) in School	Block 1	Block 2	Block 3	Block 4	Block 5
No. of Floor(s) in Block	G+2 = 3 fl.	G+2 = 3 Floor	G+2 = 3 Floor	—	—

The building is owned/occupied by ST. FRANCIS SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. (Name of Department/ Govt.) on 05/12/2024 (date of inspection) in the presence of THOMAS (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 05/12/2024 for a period of 05 (five) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. all three blocks^{of} buildings found physically
2. in good condition.
- 3.
- 4.

Issued on 05/12/24 at TANAKPUR by Laxman Singh

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature]

Name : Laxman Singh

Designation : Assistant Engg.

Name & Address of Department/ Office: _____

P.D., P.W.D., Champawat