

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer Er. A.P.S. Bisht SR. Sec
2. Name of the School St. Francis School Tankpur
3. Location with name of Education District/ Sub. District Tankpur Champawat
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
- | | Lenght | Breadth | Height |
|-------------------------------|--------|---------|---------------|
| 1 - Main Building (Permanent) | 79.86 | 9.75 | 13.72 (meter) |
| 2 - New Block (Masonry) | 26.21 | 8.53 | 13.72 (Meter) |
- Ground Floor + 2 Floor Building
5. Period for which the certificate is issued 20/12/2019 to 19/12/2020
6. Nature of defects, if any
- a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

R.C.C. Column & Beam
Conc. Piller with Intermediate
Wall with Brick
58 No Doors & 105 window.
Doors - 4 Aluminium 12 Iron & 2 Ply
wood
window - 58 Aluminium & 8 Iron
↳ R.C.C. Roof
No
No
Yes
Yes

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 20/12/2019 and
found to be fit / unfit to conduct classes, for the period 19/12/2020 for the
reasons stated above.

Place Tankpur
Date 20/12/19

(Seal)

A.P.S. Bisht
Assistant Engineer